



Services and accessories

Adaptor plates and blanking plugs

- Adapter plates avoid bearing stress for standard connectors. It assures that stress from the connector towards the glass around the edges of the drill hole is deducted over a wider area.
- Material of adaptor plates should match with connector to avoid corrosion (titanium, stainless steel and brass available)
- Blanking plugs for common hole sizes available to expand functionality of the sphere.

The already built-in o-ring of a common connectors is located too close to the outer edges of the drill hole and present a high risk of glass coming off under pressure.

